

# Disaster Recovery Project Sheet

## Type of Business

Furniture Manufacturing

## Incident Description

Warehouse Fire / heavy soot contamination and fire fighting water damage to machinery.

## Damaged / Contaminated Equipment

- Pipe Benders,
- Metal Laces
- Powdercoat Baking Oven

## Description of Recovery

- Stabilisation of equipment
- Transport off site
- Dismantling of machinery and evaluation parts to be replaced
- Report to Loss Adjuster
- Decontamination of Equipment using Dry Ice Blasting and chemical detail cleaning
- Replacement of hydraulic & pneumatic hoses, valves and cylinders
- Replacement of belts, gauges, electrical switches, damaged parts
- Overhaul of electrical motors
- Repainting of equipment
- Lubrication, testing and handover

## Equipment Replacement Value

\$2,000,000

## Total Recovery Cost

\$50,000

## Recovery time to restart of business

2 weeks

## Total Recovery Time

3.5 weeks

## Furniture Manufacturing



Pipe Bender BEFORE



Pipe Bender AFTER



Band Saw BEFORE



Band Saw AFTER